This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.






FIG. 3




FIG. 4

質問内容詞	羊細		
質問番号	HCL-0012	受付日	2000/02/03
回茶要求日	明日中	状況	顧客回答済
機器名	Steam Turbines	関連質問番 号	
作名	SCV Sticking Problem	電子会議室	
関連質問資 料		-	
質問(英文)	business trip to Edmonton tomorrow. Best regards, JJActon	XED4 will havition then EPC egiven a prelir ngs but that wiswer Center a sible please ser	e brief maintenance outage thi would like some details so that minary verbal reply that we will e will consult with T-Pukei. Ind also by fax and reply this evening as I will
質問(和文)	EPCから、高温用grease をSCVカムシャフト・ブッシンリ付け口をHTCが推奨するかとの問い合わせを受ける期停止をします。もしHTCが推奨するというなら、今週求しています。 私は以前、グリースをオイルレス・ブッシングに使うことでみますと口頭で返答しました。TSAアンサーセンタース または電子メール ドモントンに出張に行くため、できましたら今晩にも返 JJActon	た。この週末 末に取り付けを とにはあまり登り からそちらのこ	RICXED4は点使機能のためにを 行なえるように、その要領を要 応できないが、T-Pukellに相談し
	We would like to reply as below. 1) The camshaft bushing is oil-less bushing No.500.1 not used for this bushing type. HTC does not have such an experience as what EP 2) Our recommendation is that to conduct hot check immediately after stopping the turbine. The hot check means to conducted to confirm that servo-motor can move smoothly to both open and Please pay a special attention when the servo-motor Best Regards,	C intends to d k : SCV and close direction	ko
信老	TGS/ Hotta		
UE! 15	1		

5 / 16

FIG. 5(a)









FIG. 5(b)











10 / 16

FIG. 8




FIG. 9

Answer ताराव शारक		NPUT NOUTRY	LOGOEE	
General	General Information	(Category:INF	ORMATIO	N) .
Information	FileName	Update Day	File Size	File Type
Please Select Category For	Turbine,PPT	2000/01/08	149.5(KB)	PPT File
Answer Center				
CALENDER Global Service				•
INFORMATION INSTRUCTION				

FIG. 10

enu buttons above before send
3

FIG. 1.1




FIG. 12




FIG. 13

Answer Go 【共通協設 【TSA 取用協設	揭示版	eria Ee	阿達URL 回答作成	MOX. OBXE	HOOK	<u> </u>	27会型 直	LOGOFF		
	7		L An	swer	Cen	ter				- 41
		Pe		OGIN フード女王	3				<u> </u>	42
							•			

FIG. 14




FIG. 15

		根据		成 回言文 版 回言文	1025	<u>システム</u> 査理	全工会员 基	LOGOFF
背報	黄岡内容	一實					·	
	黄凤香号	金姓名	事業所名	#8	tt52	爱付日	囚答要求日	電子金額室
	開選党開党科	AICO	doc		,			
_	回表(英文) (基文/和文表示		-					
\equiv	# #							
	東盟日				22			
	夏香 作	宴依賴	CSVES	詳報表 方	Ř.		F	
		<u></u>						 -

FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24

			4
([testrone]			
Deer Sir.			
Answer Center received your inquiry by e-mail. Be comment to your inquiry so T. E.A Metter and se send reply is follows to			•
Inquiry, No : LINEW -004			
Subject: (test)		
Inquiry: [test	3		
Preser : [toot	1		
Please contact with us if you have any questions or comments.		•	
Bost regards. Hikoru Ikoda			_
Senior Engineer			
#*************************************			
•			
•			

FIG. 25

(管理会享用标题) (管理会享用标题)	7	FUXIN	PERM		IN EL	以 LOSOFF
アドレス板 ユー	プログ 所属アル	##S	* * 5	# W	兵名	EJ-A
\$118 (1199) A.	•• gt 7			ατ∓		
Umr0 / Umrog	• at∓			OT∓		
A MUTICAL CONTRACTOR	u ST ₹		. '	अ 🖚		•
	***** ST **			ST ∓		•
Purts	TGS			ros		<u> </u>
氏名(漢字)	TG9-			TOS		
5.8 (bV2)	TO9-		i	тав		<u> </u>
H #	TOS-	1		+100	ME AN	

	86									
84	RESULT OF RETRIEVAL (EXAMPLE OF ANSWER)	COUNTERMEASURE	ADHIBIT REPAIR BY WELDING	ATTACH A BALANCE WEIGHT	ADJUST ALIGNMENT	PERFORM HONING PROCESS IN PERIODIC INSPECTION	•	•		•
26 g5		CAUSE/	LARGE THERMAL STRESS	UNBALANCE	DEVIATION IN ALIGNMENT	DEPOSIT OF SCALE	•	5	•	•
80, 83 FIG. 26		PHENOMENOM	CRACKING AT MAIN COMBUSTION CHAMBER	LARGE VIBRATION	LARGE VIBRATION	MOVING BLADE VIBRATION AMPLITUDE	•		o	•
	RETRIEVAL CONDITIONS	PORTION OF COMPONENT	COMBUSTOR	BEARING	BEARING	MOVING BLADE	•	•	•	G
, 81		NAME OF / COMPONENT	GAS TURBINE	GAS TURBINE	GAS TURBINE	STEAM TURBINE	•	•	•	•